

2-11-15

(b) (6), (b) (7)(C) called at approx 10:17 one of the farm labor had seen (b) (6), (b) (7)(C) looking at 2 bridges on Litton Road around her house. Litton road has 2 bridges out and no thru traffic from HWY 61 to Herbison Road. We had a trail cam on Litton Road just East of Herbison. (b) (6), (b) (7)(C) was on this bridge at 10:17AM. We have repaired a line on this bridge two times already.

2-12-15

At approx 4:24PM (b) (6), (b) (7)(C) saw (b) (6), (b) (7)(C) on turn row at a bridge on Hwy 448. Approx 5:00 (b) (6), (b) (7)(C) hear loud noise and had no water. We looked for leak from 5:00PM to 11:30PM did not find leak. 2-14-15 Found shot line on Dixon Road at same location that was shot before (11-20-14). (b) (6), (b) (7)(C) was on scene for Bolivar SO case number 2015020044. Parts used 60 ft 4" pipe 2 4" knock on.